



Inspection Report

Report Date 19/03/2008

Company Geothermal-Solar
Address Longston Lodge, Kilgowan,
Kilcullen, Co.Kildare
Thermographer Erik Vaughan

Customer Demo
Site Address
Contact Person




Image and Object Parameters		Text Comments
Camera Model	FLIR ThermaCAM B2	
Image Date	2008:03:13 12:03:45	
Image Name	IR_0123.jpg	
Emissivity	0.96	
Reflected Temperature	23.0 °C	
Object Distance	2.0 m	

Description

This image shows the capability of thermal imaging to detect the level of fluid in a container i.e. tank level detection