



# Inspection Report

**Report Date** 19/03/2008

**Company** Geothermal-Solar  
**Address** Longston Lodge, Kilgowan,  
Kilcullen, Co.Kildare  
**Thermographer** Erik Vaughan

**Customer** Demo  
**Site Address**  
**Contact Person**





Image and Object Parameters		Text Comments
Camera Model	FLIR ThermaCAM B2	
Image Date	2008:03:19 10:58:36	
Image Name	IR_0133.jpg	
Emissivity	1.00	
Reflected Temperature	20.0 °C	
Object Distance	2.0 m	

Description
Image shows an area of thermal bridging above window. Thermal Imaging is highly useful for building energy loss analysis.